

POWDERCOAT

1. Carefully remove any loose surface deposits with a wet cloth or sponge.
2. Proceed to clean by gently rubbing the surface with a clean, soft non-abrasive cloth and a dilute solution of a mild detergent in warm water to remove dust, salt and other deposits.
3. For more stubborn stains use only recommended solvents on the affected area, e.g. Isopropyl alcohol (IPA) or methylated spirits, and rinse off with clean water.
4. Rinse the surface thoroughly after any cleaning with clean fresh water to remove any detergents or solvents, as any product sitting on the surface may impact the finish.

DO NOT Rub powder coated surfaces excessively, especially metallic finishes, as this may mark and damage the surface.

DO NOT Use aggressive solvents like turpentine, white spirits, thinners, kerosene or citrus based cleaners as these may mark or impact the surface.

ALWAYS Ensure the cloth or sponge is clean, as anything on the surface can mark the Powdercoat.

RECCOMENDED CLEANERS:

3M Stainless Cleaner and Polish

